

Repair Parts & Prices


No.	Part No.	Qty	Description	Price	No.	Part No.	Qty.	Description	ı	Price
1.	5803	1	Handle Tube Weld	24.95	7.	3756	2	Fixed Caster	per	30.15
2.	3755	4	Swivel Caster	per 30.15	8.	4949	2	Bar Spacer	per	3.50
3.	10071B	3	Channel Brace	per 18.00	9.	4943B	2	Base Plate (Right)		75.00
4.	1318	49	5/16" Washer	per .63	10.	4962	49	Screw Slotted 5/16-18	per	.50
5.	1630	49	5/16" Lock Washer	per .63	11.	4945B	2	Top Shelve	per	75.00
6.	523	49	5/16" Hex Nut 5/16-18	per .63	12.	4946B	1	Tray Plate		49.00

Order parts from your distributor or jobber. When ordering parts always give the following information: *Part Number, Description and Serial Number of Your Machine.*






WC-8 WHEEL WEIGHT CART ASSEMBLY INSTRUCTIONS



Attach the 2 TOP SHELVES (item # 11 on the left) together as shown using a total of 10 screw assemblies (item #'s 10,6,5 & 4)




Attach the middle CHANNEL BRACE (item # 3) between the 2 MIDDLE CASTERS (item # 2) ,the 2 SPACER PLATES (item # 8) and the bottom of the BASE PLATES (item #9). Thread 4 screw assemblies (per caster) through the 4 fore mentioned components


Connect the HANDLE TUBE

WELD (item # 1) to the

BASE PLATES (item #9) at

bolt assemblies.





Use 1 CHANNEL

BRACE on each

PLATES. And 2

CORNER CASTERS per CHANNEL BRACE

Attach the top lip of the 2BASE PLATES (item # 9 on the left) to the previously attached # 11's, with 5 screw assemblies each. Attach item # 12 in the center of the 2 #9's using 10 screw assemblies.

